

TPC1:CoaxialAdapterBoard 6080-008

modified 2-Nov-04: notches

notes: all traces are on component side (top)
back side has full ground plane
all holes are 0.035, plated through
unconnected holes are connected to the
ground plane with thermal isolation

